



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Phares_1_21035084710000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Phares_1_21035084710000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 1292.

<https://scholarworks.wmich.edu/pure/1292>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Phares_1_21035084710000

API 21035084710000

Permit Number 8471

Lease Name Phares

Well Number 1

County Clare

Township 20N

Range 06W

Section 32

2021 DEQ or Pure co_name Oxy USA, Incorporated

Pure Number 354

Latitude 44.08649

Longitude -85.05708

Form 24-10M-11-138-P THE PURE OIL COMPANY

WELL REPORT—OUTSIDE OPERATIONS

Winterfield Field

SERIAL NO. 354

STATE Michigan ~~OK~~ CO. Clare

OPERATOR Cities Service Oil Co.

FARM Phares WELL NO. 1


TWP. Winterfield S. 32 T. 20N R. 6W
~~XXXXXX~~LOC. C W $\frac{1}{2}$ NW NE

MAP NO. CO-ORD. ELEV.

STATUS Plugged and abandoned 4-29-47

Total Depth 3781'

NORTH



DATE 5-14-47 SCOUT H.J.G.

DATE March 12, 1941

No. 354

STATE Michigan COUNTY Clare TWP Winterfield SEC. 32 TOWN 20 N RANGE 6 W

WELL No. 1 (SERIAL No. 354) FARM Phares ACRES

NAME OF STREAM OR WATERS QUADRANGLE C 12 NW NE

OPERATOR Cities Service Oil Company Map Winterfield Township, Clare County

660 660 Feet from North Line of Farm

" " East " " "

660 660 " " South " " "

330 330 " " West " " "

660 660 Feet from North Line of Section 1/4 1/4

" " East " " "

" " South " " "

330 330 " " West " " "

LEGEND

○ LOCATION

⊕ RIG

⊕ DRILLING

⊕ GAS WELL

● OIL WELL

● SMALL OIL WELL

⊕ DRY HOLE

⊕ DRY SHOWING OIL


⊕ DRY SHOWING GAS

⊕ ABANDONED LOCATION

⊕ ABANDONED GAS WELL

⊕ ABANDONED OIL WELL

NOTE: Below make tracing from map. (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Superintendent or Foreman.

D. C. Shackelford